L Number	Hits	Search Text	DB	Time stamp
-	86	73/862.391.ccls.	USPAT	2004/03/16 14:50
-	1	73/862\$3.ccls. and (measure and (stress tension strain) and (hook hanger) and hydraulic).clm.	USPAT	2001/04/19 13:00
_	3	73/862\$3.ccls. and (measure and (stress tension strain) and (hook	USPAT	2001/04/10 12:02
-	,	hanger handle) and hydraulic and gage)	USFAI	2001/04/19 13:02
_	6	73/862\$3.ccls. and (measure and (stress tension strain) and cable and	USPAT	2001/04/21 19:28
		hydraulic and gage)	OSIAI	2001/04/21 19.26
_	0	73/\$6.ccls. and (measure and (stress tension strain) and cable and	USPAT	2001/04/19 13:06
		hydraulic and gage and hook and V near2 shape).clm.	OSIAI	2001/04/19 15.00
_	0	73/\$6.ccls. and (measure and (stress tension strain) and cable and	USPAT;	2001/04/19 13:06
		hydraulic and gage and hook and V near2 shape)	ЕРО; ЛРО;	2001/01/19 19:00
		, , , , , , , , , , , , , , , , , , , ,	DERWENT;	
			IBM_TDB	
-	0	73/\$6.ccls. and (measure and (stress tension strain) and cable and	USPĀT	2001/04/19 13:07
		hydraulic and gage).clm.		
-	43	73/\$6.ccls. and (measure and (stress tension strain) and cable and	USPAT;	2001/04/19 13:08
		hydraulic and gage)	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	1	73/\$6.ccls. and (measure and (stress tension strain) and cable and	USPAT;	2001/04/19 13:09
		hydraulic and (gage gauge)).clm.	ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	137	73/\$6.ccls. and (measure and (stress tension strain) and (cable line wire)	USPAT;	2001/04/19 13:10
		and hydraulic and gage)	ЕРО; ЈРО;	
			DERWENT;	
	505	73/00 -11 (IBM_TDB	
-	505	73/\$6.ccls. and (measure and (stress tension strain) and (cable line wire)	USPAT;	2001/04/19 13:10
		and hydraulic and (gage gauge))	ЕРО; ЛРО;	
	!		DERWENT;	
_	4	73/\$6.ccls. and (measure and (stress tension strain) and (cable line wire)	IBM_TDB USPAT;	2001/04/19 13:14
_	, T	and hydraulic and (gage gauge)).clm.	EPO; JPO;	2001/04/19 13.14
		and nythatine and (gage gauge)).onn.	DERWENT;	
			IBM_TDB	
-	0	73/144.ccls.	USPAT;	2001/04/19 13:12
			ЕРО; ЛРО;	
			DERWENT,	
			IBM_TDB	
-	5	3839908.pn.	USPAT;	2001/04/19 13:12
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	11	(measure and (stress tension strain weigh) and (cable line wire) and	USPAT;	2001/04/19 13:18
		hydraulic and (gage gauge)).clm.	ЕРО; ЛРО;	
			DERWENT;	
	_	(IBM_TDB	2001/04/10 12 10
-	0	(measure and (stress tension strain weigh) and (cable line wire) and (v	USPAT;	2001/04/19 13:18
		near shape) and (gage gauge)).clm.	EPO; JPO;	
			DERWENT; IBM_TDB	
_	0	(measure and (stress tension strain weigh) and (cable line wire) and (v	USPAT;	2001/04/19 13:20
	J	near4 shape) and (gage gauge)).clm.	EPO; JPO;	2001/04/17 13.20
			DERWENT;	
			IBM_TDB	
-	1	(measure and (stress tension strain weigh) and (cable line wire) and (v	USPAT;	2001/04/19 13:19
		near4 shape)).clm.	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	

-	80484	(stress tension strain weigh) and (cable line wire).clm.	USPAT; EPO; JPO;	2002/07/02 09:36
			DERWENT;	
			IBM_TDB	
-	10275	((stress tension strain weigh) and (cable line wire).clm.) and measure	USPĀT,	2001/04/19 13:20
			EPO, JPO,	
			DERWENT;	
			IBM_TDB	
-	1025	((stress tension strain weigh) and (cable line wire).clm.) and	USPAT;	2001/04/19 13:20
		measure.clm.	ЕРО; ЈРО;	
			DERWENT;	
	122	/// A mana a	IBM_TDB	2001/04/10 12 21
-	122	(((stress tension strain weigh) and (cable line wire).clm.) and	USPAT;	2001/04/19 13:21
		measure.clm.) and (gage gauge).clm.	EPO; JPO;	
			DERWENT; IBM_TDB	
_	11	(((((stress tension strain weigh) and (cable line wire).clm.) and	USPAT;	2001/04/19 13:21
_	''	measure.clm.) and (gage gauge).clm.) and jack	EPO; JPO;	2001/04/19 13.21
		measure.onn.) and (gage gauge).onn.) and juok	DERWENT;	
			IBM_TDB	
_	39113	(stress tension strain weigh) and (cable wire).clm.	USPAT;	2001/04/19 13:22
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	18	((stress tension strain weigh) and (cable wire).clm.) and measure and	USPAT;	2001/04/19 13:26
		jack and (gage gauge).clm.	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	2001/04/10 12 25
-	159546	wire near stain naear gauge	USPAT;	2001/04/19 13:27
			EPO; JPO; DERWENT;	
			IBM TDB	
_	2	wire near stain near gauge	USPAT;	2001/04/19 13:27
	_	With them beams bands	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	5	(wire cord cable) near (stain force stress) near gauge	USPAT;	2001/04/19 13:38
			ЕРО; ЛРО;	
			DERWENT;	
	146	Charles 1 and 1 an	IBM_TDB	2001/04/10 12:29
-	146	(wire cord cable) near4 (stain force stress) near4 gauge	USPAT; EPO; JPO;	2001/04/19 13:38
			DERWENT;	
			IBM_TDB	
_	109420	deflect(wire cord cable) near4 (stain force stress) near4 gauge	USPAT;	2001/04/19 13:59
		(ЕРО; ЛРО;	
			DERWENT,	
			IBM_TDB	
-	21	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect	USPAT;	2001/04/19 13:57
		deflection)	ЕРО; ЛРО;	
	1		DERWENT;	
	_		IBM_TDB	2001/04/10 12 55
-	9	((wire cord cable) near4 (stain force stress) near4 gauge) and (deflect	USPAT;	2001/04/19 13:57
		deflection) and pull	EPO; JPO; DERWENT;	
			IBM_TDB	
_	3	deflect and(wire cord cable) near4 (stain force stress) near4 (gauge	USPAT;	2001/04/19 14:02
		gage)and pull	EPO; JPO;	2501/04/17 14:02
		0.0-/ F	DERWENT;	
			IBM_TDB	

-	856	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull	USPAT; EPO; JPO;	2001/04/19 14:43
			DERWENT;	
			IBM_TDB	
-	3	deflect and(wire cable) near4 (stain force stress) near4 (measure\$4)and	USPAT;	2001/04/19 14:03
		pull	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	16	73/862.39\$.ccls. and pull and cable	USPAT	2001/04/19 14:15
-	82	73/862.451.ccls.	USPAT	2004/03/16 14:51
-	4	73/862.42.ccls. and pull and cable	USPAT	2001/04/19 14:24
-	205	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull	USPAT;	2001/04/19 14:44
		and hydraulic	ЕРО; ЛРО;	
			DERWENT;	
	38	deflect and(wire cable) and (stain force stress) and (measure\$4)and pull	IBM_TDB USPAT;	2001/04/19 14:45
-	30	and hydraulic .clm.	ЕРО; ЛРО;	2001/04/15 14.45
	1		DERWENT;	
			IBM TDB	
_	0	(deflect and(wire cable) and (stain force stress) and (measure\$4)and	USPAT;	2001/04/19 14:46
		pull and hydraulic) .clm.	ЕРО; ЛРО;	2001/01/19 11:10
			DERWENT;	
			IBM TDB	
-	1	(deflect and(wire cable) and (stain force stress) and hydraulic) .clm.	USPĀT;	2001/04/23 08:15
			ЕРО; ЈРО;	
			DERWENT;	
:			IBM_TDB	
-	6	73/862.391.ccls. and hydraulic	USPAT	2001/04/21 19:25
-	1	73/862.391.ccls. and (hydraulic).clm.	USPAT	2001/04/21 19:25
-	0	73/862\$3.ccls. and (measure and (stress tension strain) and cable and	USPAT	2001/04/23 08:46
		hydraulic and gage).clm.	LICDATE	2001/04/21 10 20
-	2	73/862\$3.ccls. and (measure and (stress tension strain) and hydraulic	USPAT	2001/04/21 19:29
	,	and gage).clm.	USPAT	2001/04/23 11:52
-	538	73/\$6.ccls. and (measure and deflection and hydraulic and gage).clm. (measure and deflection cable and hydraulic and gage).clm.	USPAT	2001/04/23 11:32
-	4	(measu\$4 and deflect\$4 and cable and hydraulic and (gauge gage)).clm.	USPAT	2001/04/21 19:32
]	12	(measu\$4 and cable near4 deflect\$4 and hydraulic and (gauge gage))	USPAT	2001/04/21 19:36
_	1	(tensiometer and cable near4 deflect\$4 and hydraulic and (gauge	USPAT	2001/04/23 11:51
	1	gage)).clm.		
_	535	(measure and deflection cable and hydraulic near4 jack and gage).clm.	USPAT	2001/04/21 19:39
-	535		USPAT	2001/04/21 19:39
-	42	(tensio\$4 and measure and deflection cable and hydraulic near jack and	USPAT	2001/04/21 19:50
		(gage gauge)).clm.		
-	3	(tensio\$4 and pull near4 test\$4 and deflection cable and hydraulic near	USPAT	2001/04/21 19:51
		jack and (gage gauge)).clm.		
-	34346	cable near4 (tension pull tes\$4)	USPAT;	2001/04/23 08:21
			EPO; JPO;	
			DERWENT,	
	2002		IBM_TDB	2001/04/23 08:23
-	3892	cable near4 (tension pull tes\$4).clm.	USPAT; EPO; JPO;	2001/04/23 08:23
			DERWENT;	
			IBM_TDB	
_	1152	tensiometer	USPAT	2001/04/23 08:46
_	1132		USPAT	2001/04/23 08:46
1_	3	("4907458" "3839908" "4989450").pn.	USPAT	2001/04/23 11:52
-	5	proceq	USPAT	2001/11/02 15:55
	2	wire near tension near meter	USPAT	2001/11/02 15:56
-	373	wire near tension and concrete	USPAT;	2001/11/02 16:30
			US-PGPUB;	
			ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	

-	68	wire near tension and concrete and hydraulic	USPAT;	2001/11/02 16:30
			US-PGPUB;	
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	68	(wire near tension) and concrete and hydraulic	USPAT;	2001/11/02 16:50
			US-PGPUB;	2001/11/02 10:50
			ЕРО; ЛРО;	
		•	DERWENT;	
			IBM_TDB	
-	25	(wire near2 tension) and concrete and hydraulic and gauge	USPAT;	2001/11/02 16:51
			US-PGPUB;	
			ЕРО, ЛРО,	
			DERWENT;	
			IBM_TDB	
	108	73/862.42.ccls.	USPAT	2004/03/16 14:51
-	T .	1		2004/03/16 14:51
-	92	73/862.391.ccls.	USPAT	2001/11/05 13:08
-	82	73/862.381.ccls.	USPAT	2004/03/16 14:51
-	0	658118.URPN.	USPAT;	2001/11/05 13:30
			US-PGPUB;	
			ЕРО, ЛРО,	
			DERWENT;	
			IBM_TDB	
	0	541850.URPN.	USPAT;	2001/11/05 13:30
-	0	341630.0Rt N.		2001/11/05 15.50
			US-PGPUB;	
			ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	8	("2872808" "3679808" "3994162").PN.	USPAT;	2001/11/05 13:40
			US-PGPUB;	
			ЕРО; ЛРО;	
1			DERWENT;	
1				
	,	5200550 HDDN	IBM_TDB	2001/11/05 12 40
-	1	5390550.URPN.	USPAT;	2001/11/05 13:40
			US-PGPUB;	
			ЕРО; ЛРО;	
			DERWENT;	
			IBM TDB	
_	1	220668.URPN.	USPĀT;	2001/11/05 14:18
			US-PGPUB;	
,			ЕРО; ЛРО;	
			DERWENT;	
		72/144 colo	IBM_TDB	2001/11/05 14 25
-	0	73/144.ccls.	USPAT	2001/11/05 14:36
-	64	73/158.ccls.	USPAT	2004/03/16 14:51
-	178	73/144	USPAT	2001/11/05 16:13
-	3	4374473.URPN.	USPAT;	2001/11/05 14:39
	-		US-PGPUB;	
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
	1	4989450.URPN.	USPAT;	2001/11/05 14:43
_	1	4767430.0IQ IV.		2001/11/03 14.43
	1		US-PGPUB;	
			ЕРО; ЈРО;	
			DERWENT;	
	1		IBM_TDB	
-	0	D297818.URPN.	USPAT;	2001/11/05 14:48
	1		US-PGPUB;	
			ЕРО; ЛРО;	
			DERWENT;	
			IBM TDB	
	1	<u> </u>	IDIM_10D	L

-	29	("D087988" "D271669" "D275087" "1780141" "2013810"	USPAT;	2001/11/05 14:48
		"3176510" "3410246" "3618379" "4163126" "4171640"	US-PGPUB,	
		"4534228").PN.	ЕРО, ЛРО,	
		,	DERWENT;	
			IBM_TDB	
_	1	4135393.URPN.	USPAT;	2001/11/05 14:56
		1100000101111	US-PGPUB;	2001/11/05 14.50
			EPO, JPO,	
			DERWENT;	
	177	(#22.450.20# #250.172.4# #270.25(1# #2.405.454# #251.240(#\ D\)	IBM_TDB	2001/11/05 15 04
-	17	("2245039" "2591724" "2723561" "3495454" "3512406").PN.	USPAT;	2001/11/05 15:04
			US-PGPUB;	
			EPO; JPO;	
			DERWENT;	
			IBM_TDB	
-	2	3879999.URPN.	USPAT;	2001/11/05 15:04
			US-PGPUB;	
			ЕРО; ЈРО;	
İ			DERWENT;	
			IBM_TDB	
-	13	(tensiometer and (wire cable)).clm.	USPAT	2001/11/05 16:15
-	5317	((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4 meter\$4) and (stress	USPAT;	2002/07/02 09:41
		tension strain weigh) and (cable line wire)).clm.	ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
_	347	(((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4 meter\$4) and (stress	USPAT;	2002/07/02 09:45
1]	tension strain weigh) and (cable line wire)).clm.) and hydraul\$4.clm.	ЕРО; ЛРО;	2002/07/02 07.45
		tension strain weigh) and (cable line whe)).chii.) and hydrauto4.chii.	DERWENT;	
	41	((((management) detected detected detected action at \$4 action at \$4 action at \$4 action \$4 acti	IBM_TDB	2002/07/02 12:40
-	41	((((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4 meter\$4) and	USPAT;	2002/07/02 13:49
		(stress tension strain weigh) and (cable line wire)).clm.) and	EPO; JPO;	
	1	hydraul\$4.clm.) and ((measur\$4 detect\$4 determin\$4 estimat\$4 sens\$4	DERWENT;	
		meter\$4) near4 (deflect\$4 deviat\$4 bend\$4))	IBM_TDB	
-	0	73/144.ccls.	USPAT;	2002/07/02 13:49
			ЕРО; ЈРО;	
			DERWENT;	
			IBM_TDB	
-	185	73/144	USPAT;	2002/07/02 13:50
			ЕРО; ЛРО;	
			DERWENT;	
			IBM_TDB	
-	3	("3174334" "3653258").pn.	USPAT;	2002/07/02 13:51
			ЕРО; ЛРО;	
			DERWENT,	
			IBM_TDB	
_	3	("4333353" "5738097" "5406854").pn.	USPĀT	2002/07/03 13:09
-	5	(hydrauli\$4 near4 (jack brac\$4 lever)) same ((wire cable strand rope	USPAT	2003/03/27 13:13
		rod) near4 (measur\$4 test\$4 meter\$4 determin\$4 sens\$4 detect\$4		
		estimat\$4) near4 (deflect\$4 displac\$4 mov\$4 bend\$4))		
-	12	(hydrauli\$4 near4 (jack brac\$4 lever)) same ((wire cable strand rope	USPAT	2003/03/27 13:13
]	rod) near4 (measur\$4 test\$4 meter\$4 determin\$4 sens\$4 detect\$4		
	1	estimat\$4) near4 (deflect\$4 force displac\$4 mov\$4 bend\$4))		
-	9	(hydrauli\$4 near4 (jack brac\$4 lever)) same ((wire cable strand rope	USPAT;	2003/03/27 13:17
	1	rod) near4 (measur\$4 test\$4 meter\$4 determin\$4 sens\$4 detect\$4	US-PGPUB;	2003/03/27 13.17
		estimat\$4) near4 (deflect\$4 displac\$4 mov\$4 bend\$4))	EPO; JPO;	
		сышафт) псагт (аспесть авриаст шоут вспата))		[
1			DERWENT;	
	_		IBM_TDB	2002/04/02 20 00
-	0	equation near4 calcualt\$4 near4 tension\$4 near4 deflect\$4	USPAT	2003/04/02 20:09
-	0	equation near4 calcualt\$4 near4 tension\$4	USPAT	2003/04/02 20:10
-	146	equation near4 calculat\$4 near4 tension\$4	USPAT	2003/04/02 20:10
-	6	equation near4 calculat\$4 near4 tension\$4 near4 (deflect\$4 bend\$4)	USPAT	2003/04/02 20:12
-	4	(equ\$5 near4 calculat\$4 near4 tension\$4 near4 (deflect\$4 bend\$4))	USPAT	2003/04/02 20:18
L-	4	(force near4 calculat\$4 near4 tension\$4 near4 (deflect\$4 bend\$4))	USPAT	2003/04/02 20:18

Search History 3/18/04 11:46:50 AM Page 5

-	111	73/862.391.ccls.	USPAT	2004/03/16 15:06
-	92	73/862.451.ccls.	USPAT	2004/03/16 14:53
-	110	73/862.42.ccls.	USPAT	2004/03/16 16:51
-	109	73/862.381.ccls.	USPAT	2004/03/16 14:51
-	68	73/158.ccls.	USPAT	2004/03/16 14:52
-	86	73/862.454.ccls.	USPAT	2004/03/16 14:53
-	31	(73/862.391.ccls. 73/862.451.ccls. 73/862.42.ccls. 73/862.381.ccls.	USPAT	2004/03/16 15:29
		73/158.ccls. 73/862.454.ccls.) and ((tension\$4 pull\$4 stretch\$4 draw\$4	·	
		stress\$4) near4 (deflect\$4 bend\$4 deformat\$4 force load\$4) near4 (wire		
		cable rope))		
-	304	73/\$6.ccls. and ((tension\$4 pull\$4 stretch\$4 draw\$4 stress\$4) near4	USPAT	2004/03/16 15:30
		(deflect\$4 bend\$4 deformat\$4 force load\$4) near4 (wire cable rope))		
-	33	73/862.46.ccls.	USPAT	2004/03/16 16:51